



Carabineers found defective. (Sticky gate.)

- The carabineers were brought to the manufacture and once they were oiled two of then functioned properly one did not.
- The carabineers will not last in our work environment.
- Bay will be removing triple action carabineers from service and replacing with double locking snap hooks.