 PRODUCING CONFIDENCE

danos 

Material Handling

Andrew Rodrigue


www.danos.com

August 25, 2015

Material Handling

NW Hull Cross Sectional View

(Ladder Access Only)




Bundle struck center of hull column. Bundle stayed together until impact. Upon impact bundle tubes broke apart and one tube landed within 2' of the worker at Level 0.

tubes were oriented vertically when suspended by hoist

1000# sling wrapped 2-4 times with end put through loop

1/4" rope tied around end of bundle with tag line



Material Handling

- Shell purchased (3) scaffolding tote bags to transport scaffold poles up / down the hull columns. The bags have been sent out to WD 143.



Material Handling

IP and another Rigger were attempting to carry a pallet jack down the staircase. During the process of lifting and carrying, The IP felt a small pop in his knee



Material Handling

- A Danos rigging crew working offshore was tasked with loading some heavy duty lockers into a metal 8' x 24' cargo basket in preparation to send onshore. While standing inside the basket in order to manually place the locker into position, one of the workers accidentally tripped on a weathered sheet of ply-wood .



Material Handling



- Get Help
 - Use carts, dollies, forklifts, baskets, hoist, and crane to move materials
 - When lifting a load more than 50lbs, get help from another worker
 - Use carrying tools with handles to carry odd-shaped loads
 - Use proper lifting techniques

TAKE YOUR TIME!!